

The Hammond River Watershed Management Plan



Prepared By:
Sarah Campbell and Shawn Prosser
Hammond River Angling Association
10 Porter Road, Nauwigewauk, NB
E5N 6X1

Your Environmental Trust Fund at Work

New  Nouveau
Brunswick




Figure 1. The Hammond River Watershed. The majority of the watershed is considered to be A class water, indicating excellent water quality. However, there are still a number of brooks with B or C classes attached to them. Protecting the A class sections and improving the quality of the B and C class brooks is a major concern for the HRAA.

Table of Contents

List of Figures	vi
List of Tables	xiii
I. Acknowledgements	1
II. Introduction to the Watershed Management Plan	
A. HRAA History	2
B. Water Classification and Watershed Management	4
C. Fisheries Management	6
III. HRAA Methods	
A. Stream Habitat Assessments	10
B. Illegal Dump Cleanups	16
C. Water Quality Assessments and Benthic Analysis	17
D. Riparian Zone Assessments and Restoration	18
E. Sediment Research	20
F. Salmon Population Assessments	
1. Redd Counts	22
2. Juvenile Density Surveys	24
3. Adult Assessments	25
G. Juvenile Salmon Stocking	26
IV. Results (Data Compilation for 22 Eco-Reaches)	
A. Main Stem of the Hammond River	
1. Markhamville	28
2. Mill Brook Area	32
3. Tabor Bridge	36
4. Cusack’s Bridge	42
5. Smithtown Bridge	46
6. French Village Bridge	50
7. Bridge Pool by HRAA	56
B. Major Tributaries of the Hammond River	
1. North Branch	60

2. Mill Brook	64
3. Hanford Brook	68
4. Germaine Brook	74
5. Scoodic Brook	78
6. South Stream Brook	84
7. Salt Springs Brook	90
8. Bradley Brook	96
9. Palmer Brook	102
C. Minor Tributaries of the Hammond River	
1. Fowler Brook	108
2. McGonagle Brook	114
3. Donnelly Brook	118
4. Titus Brook	122
5. Brawley Brook	126
6. Bater Brook	130
V. Conclusions and Discussion	
A. Water Classification	136
B. Fisheries Management	144
C. Watershed Management	148
VI. Glossary of Terms	157
VII. References.....	162
VIII. Appendices	
A. Juvenile Density Survey Results	164
B. Redd Count Data	170
C. Stream Habitat Assessment Results	172
D. Water Quality Results	176
E. Juvenile Salmon Stocking Data	199
F. Bacterial Sampling Results	201
G. Adult Assessments	208
H. Sediment Studies	210
I. Benthic Analysis	212

List of Figures

Figure 1. The Hammond River Watershed. The majority of the watershed is considered to be A class water, indicating excellent water quality. However, there are still a number of brooks with B or C classes attached to them. Protecting the A class sections and improving the quality of the B and C class brooks is a major concern for the HRAA.	iii
Figure 2. Angler casting across the Smithtown pool, during the time when Atlantic salmon were of great abundance in the system. <i>Photo Unknown</i>	2
Figure 3. Jim Gillespie, former HRAA president, engaging youth through the art of fly fishing. Jim has helped to create many stewards of the river system and the environment.	3
Figure 4. Map of the Hammond River eco-reaches showing boundaries of each tributary eco-reach and main stem eco-reach. Map created By Sarah Campbell and Shawn Prosser using DNR GIS Data 2009.	4
Figure 5. Aerial view of the French Village eco-reach at Deep Hole pool. Flight courtesy of Arnold Boer, <i>Photo: S. Mackay</i>	5
Figure 6. A seasoned angler looks to hook a prized Salmon at the Smithtown pool.....	8
Figure 7. HRAA uses two simple methods for determining the overall width of the given water body; the wet width and channel width. Depth is also taken across the same spans as the width, they are taken at the ¼ mark, ½ mark and ¾ mark for both widths.	12
Figure 8. Riffles help to input oxygen into the water and decrease water temperatures improving aquatic habitat. Riffle on Donnelly Brook <i>Photo S. Prosser</i>	12
Figure 9. Pools often contain a higher concentration of fish as the available habitat is high and nutrients are abundant. Mill Brook <i>Photo S. Prosser</i>	13
Figure 10. Young environmental leadership student Greg Torrey collecting GPS points along stream habitat assessment on Scodic Brook, summer 2006. <i>Photo S. Campbell</i>	15
Figure 11. Debris removed from a small section of stream, clearly showing the importance of good aquatic stewardship. <i>Photo S. Mackay</i>	16
Figure 12. Young environmental enthusiast participating in a community riparian planting day. <i>Photo S. Prosser 2008</i>	18
Figure 13. Planting sites located along the Hammond River where significant erosion has been noted. <i>Map drawing S.Campbell</i>	19
Figure 14. Salt Springs Brook site of large scale erosion causing significant sediment loading in the stream below. <i>Photo S. Prosser</i>	19

Figure 15. Effects of a small ditch feeding sediment during a moderate rain event into Palmer Brook. <i>Photo S. Campbell</i>	20
Figure 16. Sarah Campbell installing incubation baskets during late fall, in Salt Springs Brook. <i>Photo S. Mackay</i>	21
Figure 17. Water samples taken during heavy rain events along Palmer Brook showing heavy sedimentation caused by erosion and runoff from industrial sites. The furthest upstream samples are on the left and work downstream to the right in this photo. <i>Photo S. Campbell</i>	21
Figure 18. Christa Carpenter, Environmental Technician 2004, places sign along known ATV trails to protect Salmon eggs during sensitive incubation period. <i>Photo. S. Mackay.</i>	22
Figure 19. Volunteers and staff use their vast knowledge of Hammond River salmon populations to conduct a Redd count along many tributaries. Barry Carr 2004, current president of the HRAA counting Redds along North Branch.	23
Figure 20. Brook trout caught during 2007 juvenile density survey. <i>Photo. G Sayer.</i>	24
Figure 21. Image taken during visual assessment of Salmon holding in a pool along the Hammond River in the fall of 2006, <i>Photo Andrew Giffin</i>	25
Figure 22. Female grilse collected from Palmer Brook in 2007. Her eggs were later removed and fertilized and used for stocking, while she was released back into the Hammond River.	26
Figure 23. Markhamville facing up river of the Hammondvale Bridge. Well vegetated banks are present on either side of the river casting a significant amount of shade on the river. <i>Photo S. Prosser</i>	26
Figure 24. The eco-reach of Markhamville on the furthest section of the Hammond River, New Brunswick. Map drawn using SNB GIS. <i>Map S. Campbell</i>	29
Figure 25. Work performed along the Markhamville eco-reach on the upper Hammond River. Map drawn using DNR GIS data. <i>Map S. Campbell</i>	30
Figure 26. The Hammond River at its furthest reach, Markhamville, New Brunswick. <i>Photo S. Prosser</i>	31
Figure 27. Upriver aspect of the Hammond River below Mill Brook. A strong riparian zone is present on the right bank while the left consists mainly of grasses and small shrubs. <i>Photo: S. Prosser.</i>	32
Figure 28. The Mill Brook region eco-reach, located on the upper Hammond River, New Brunswick. Map created using SNB GIS data <i>Map S. Campbell</i>	33
Figure 29. Work performed on the Mill Brook area eco-reach. Map drawn using DNR GIS data, <i>Map S. Campbell</i>	34

Figure 30. Many new channels and splits are beginning to appear along the Mill Brook region, with little vegetation to slow it down. <i>Photo S. Prosser</i>	35
Figure 31. An up-river view of the Tabor Eco-reach. Photo taken summer 2008 prior to the removal of the old Bailey bridge. Upham, New Brunswick <i>Photo: S. Prosser</i>	36
Figure 32. Boundaries of the Tabor Bridge region eco-reach, located on the upper Hammond River, New Brunswick. Map created using SNB GIS data <i>Map S. Campbell</i>	37
Figure 33. Work performed along the Tabor bridge eco-reach. Map drawn using DNR GIS data, <i>Map S. Campbell</i>	38
Figure 34. Unique rock feature above the Tabor Bridge pool prior to the installation of the bailey bridge replacement of 2008. <i>Photo unknown</i>	39
Figure 35. Cusack’s Bridge eco-reach, photo taken with an up-river view from Cusack’s Bridge. <i>Photo S. Prosser</i>	42
Figure 36. Cusack’s eco-reach covering Smithtown and Titusville, New Brunswick. Map created using DNR GIS data, <i>Map S. Prosser</i>	43
Figure 37. Work performed along the Cusack’s eco-reach. Map drawn using DNR GIS data, <i>Map S. Campbell</i>	44
Figure 38. Smithtown eco-reach up-river from the covered bridge, showing shallow water levels and a strong gravel/rock substrate. <i>Photo S. Prosser</i>	46
Figure 39. Boundaries of the Smithtown eco-reach, located on the mid Hammond River, New Brunswick. Map created using SNB GIS data by Sarah Campbell, HRAA 2009.....	47
Figure 40. Work performed along the Smithtown eco-reach. Map created using DNR GIS data, <i>Map S. Campbell</i>	48
Figure 41. Common Shiner found during the 2008 electro-fishing survey conducted along the Smithtown eco-reach. <i>Photo S. Campbell</i>	49
Figure 42. An up-river aspect of the French Village eco-reach, showing strong right banks with heavy vegetation and a weak left bank with minimal vegetation. <i>Photo S. Prosser</i>	50
Figure 43. French Village eco-reach spanning through French village, New Brunswick. Map drawn using DNR GIS data, <i>Map S. Campbell</i>	51
Figure 44. Work performed along the French Village eco-reach. Map created using DNR GIS data, <i>Map S. Campbell</i>	52

Figure 45. Results of a truckload of French fries spilling into the Hammond River at the French Village Bridge. This spill resulted in an oily film developing over the downstream portions of the river and a thick build up of decomposing material floating to the surface. <i>Photo S. MacKay 2006</i>	53
Figure 46. An up-river aspect of the HRAA eco-reach, showing deep runs with strong right banks and weak left banks. <i>Photo A. White</i>	56
Figure 47. Eco-reach of HRAA located in Nauwigewauk, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	57
Figure 48. Work performed along the HRAA eco-reach, with a strong emphasis on the confluence of Palmer Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	58
Figure 49. North Branch eco-reach located in the North-western point of the watershed, New Brunswick. <i>Photo S. Prosser</i>	60
Figure 50. North Branch in relation to the Hammond River, created using DNR GIS data. <i>Map S. Campbell</i>	61
Figure 51. Work performed along Mill Brook and its tributaries. Map created using DNR GIS data. <i>Map S. Campbell</i>	62
Figure 52. A long stretch of the North Branch teeming with beaver dams and large holding pools for Salmon and trout. <i>Photo S. Prosser</i>	63
Figure 53. Mill Brook eco-reach located in Hillsdale, New Brunswick. <i>Photo S. Prosser</i>	64
Figure 54. Mill Brook and its major tributaries in relation to the Hammond River. Map created using DNR GIS data, <i>Map S. Campbell</i>	65
Figure 55. Work performed along Mill Brook and its tributaries. Map created using DNR GIS data. <i>Map S. Campbell</i>	66
Figure 56. Large natural pool formations below cascades creating optimal resting habitat. <i>Photo S. Prosser</i>	67
Figure 57. Lower Hanford Brook, with an up river perspective showing strong banks and dense riparian zones. <i>Photo S. Prosser</i>	68
Figure 58. Hanford Brook eco-reach and its many tributaries in relation to the Hammond River. Map created using DNR GIS data, <i>Map S. Campbell</i>	69
Figure 59. Work performed along Hanford Brook and its two major tributaries. Map created using DNR GIS data, <i>Map S. Campbell</i>	70
Figure 60. Sarah Campbell, Watershed Management Specialist 2008, taking fall samples of Hanford Brook to be used in the watershed ratification efforts. <i>Photo S. Prosser</i>	71

Figure 61. Upper Germaine Brook, note the strong substrate and highly stabilized banks covered in mature trees. <i>Photo S. Campbell</i>	74
Figure 62 Germaine Brook in relation to the Hammond River covering Barnesville and Titusville. Map created using DNR GIS data, <i>Map S. Campbell</i>	75
Figure 63. Work performed along Germaine Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	76
Figure 64. Lower Scoodic Brook, boasting a strong riparian zone on both sides of the brook, while ahead (downstream), water quality has been found to be that of a “C” class brook. <i>Photo S. Prosser</i>	78
Figure 65. Scoodic Brook in relation to the Hammond River, Upham, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	79
Figure 66. Work performed along the Scoodic Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	80
Figure 67. Sandy Mackay, Director of Education and Public Outreach 2008, assisting in the retrieval of sediment tubes placed in Scoodic Brook, monitoring incubation survival of salmon eggs. <i>Photo S. Campbell</i>	81
Figure 68. South Stream brook with lush foliage covering banks and casting shade on the passing water. <i>Photo S. Prosser</i>	84
Figure 69. South Stream Brook in relation to the Hammond River, Upham, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	85
Figure 70. Work performed along the South Stream Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	86
Figure 71. Summer field technicians, Denise Mowry and Stewart Tonge 2005, analyzing result of the first pass electro-fishing on South Stream Brook. <i>Photo S. Prosser</i>	87
Figure 72. Salt Springs Brook accessed at the end of Meadow Lane, through the old Titus farm.....	90
Figure 73. The large span of Salt Springs Brook in relation to the Hammond River, Upham New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	91
Figure 74. Work performed along the Salt Springs Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	92
Figure 75. Mid section of Bradley Brook showing silt banks and dense alder cover. <i>Photo S. Prosser</i>	96
Figure 76. Bradley Brook in relation to the Hammond River, French Village, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	97
Figure 77. Work performed along Bradley Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	98

Figure 78. Mid section of Palmer Brook, with many digger logs in place to increase dissolved oxygen. <i>Photo S. Prosser.</i>	102
Figure 79. Palmer Brook in relation to the Hammond River. Map created using DNR GIS data, <i>Map S. Campbell</i>	103
Figure 80. Work performed along the Palmer Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	104
Figure 81. A group of students stop to take a look at one of Palmer Brook’s most influential trees, the Silver maple. <i>Photo S. Mackay</i>	105
Figure 82. Environmental leadership students assisting in data collection while learning valuable lessons in environmental stewardship. Student volunteers from left to right: Chris Daigle, Andrew Atkinson, and Kyle Logan 2006. <i>Photo S. Prosser</i>	106
Figure 83. Fowler Brook following its long passage through densely stocked alder swale. <i>Photo S. Prosser</i>	108
Figure 84. Fowler Brook in relation to the Hammond River. Map created using DNR GIS data, <i>Map S. Campbell</i>	109
Figure 85. Work performed on the Fowler Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	110
Figure 86. Chamber number one located directly above Fowler Brook. Winter 2009 chamber one failed and a large brine spill occurred over several hours prior to its discovery. Sarah Campbell Watershed Management Specialist 2009 conducted a full impact assessment, with no reported fish kill. <i>Photo S. Campbell</i>	111
Figure 87. Slow moving waters of McGonagall Brook. A dense vegetative covering and many fresh springs help to keep this small brook cool during peak summer temperatures. <i>Photo S. Prosser</i>	114
Figure 88. McGonagall Brook in relation to the Hammond River, Upham, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	115
Figure 89. Work performed along Mcgonagle Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	116
Figure 90. Juvenile density surveys have not been conducted on Mcgonagle Brook however, the abundance of fish was evident throughout the stream habitat assessment. This small school of black nose dace was one of many seen along the 1000 Metre assessment. <i>Photo A. White</i>	117
Figure 91. Pristine Donnelly Brook as it passes through the hillsides into the Hammond River. <i>Photo S. Prosser.</i>	118
Figure 92. Donnelly Brook in relation to the Hammond River, Upper Barnesville, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	119
Figure 93. Work performed along the Donnelly Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	120

Figure 94. Large rock formations were some of the many inspiring spectacles found along the pristine Donnelly Brook. <i>Photo S. Prosser</i>	121
Figure 95. Shallow and slow moving Titus Brook, above route 860. <i>Photo S. Prosser</i>	122
Figure 96. Titus Brook in relation to the Hammond River. Map created using DNR GIS data, <i>Map S. Campbell</i>	123
Figure 97. Work performed along Titus Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	124
Figure 98. Department of Transportation replaced a large dated corrugated steel culvert, through which Titus Brook passed, with a fitted concrete culvert. The newly constructed culvert contains many small indentations allowing water to pool within the culvert and fish to rest. <i>Photo J Gibbons</i>	125
Figure 99. Narrow portion of lower Brawley Brook with moderate channel depths and still moving water. <i>Photo: S. Prosser</i>	126
Figure 100. Brawley Brook in relation to the Hammond River, Damascus, New Brunswick. Map created using DNR GIS data, <i>Map S. Campbell</i>	127
Figure 101. Work performed on Brawley Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	128
Figure 102. 2006 Summer field crew, lead by Tom Floyd, baffled at the discovery of a mill turbine in Brawley Brook. Historically many of the brooks along the Hammond were pooled and mills were created. <i>Photo S. Prosser</i>	129
Figure 103. Bater Brook in the summer, low flows dominate and large pools have been through downed-woody material. <i>Photo: S. Prosser</i>	130
Figure 104. The land around Bater Brook is primarily made up of forest, although it does pass under a number of roads and the Mackay Highway. Development of a new rural settlement is not visible on this map. <i>Map by S. Campbell</i>	131
Figure 105. Work performed along Bater Brook. Map created using DNR GIS data, <i>Map S. Campbell</i>	132
Figure 106. Local developers have are respecting Bater Brook by creating a nice walking trail and bridge. This attempt allows the future land owners to share in the enjoyment of the brook. <i>Photo S. Prosser</i>	133
Figure 107. Renforth construction worked with HRAA staff and DENV to re-establish a degraded gravel pit reducing large flows of sediment to Palmer Brook. Photo on the left shows the Renforth pit in February of 2008 and the photo on the right show the same location in July 2008. A settling pond and standpipe was installed to regulate water runoff and prevent the sedimentation of Palmer Brook. <i>Photos S. Campbell</i>	137

Figure 108. Average fry densities at the historical sites from 1979-2008. For each given year the average of was taken of all assessed sites. This could be from one to five sites, depending on the year. A clear decline in average fry densities is evident following the huge spike in 1997. Graph by S. Campbell142

Figure 109. Bar graph depicting the average density of each species identified in the Hammond River Watershed during 2008 electro-fishing surveys.144

Figure 110. In late summer of 2008 contractors began to replace the Tabor Bridge. Photo shown of strong fall flooding taken following heavy rain events of late October 2008. Monitoring was conducted by HRAA staff and DENV to limit the impact of the construction on the river. *Photo T. Benjamin*149

Figure 111. A group of high school students volunteering time and energy to help plant thousands of sapling trees in the HRAA field, spring 2008. *Photo G. Sayer*.....150

Figure 112. In the summer of 2001 staff and volunteers worked tirelessly to clean a dumpsite along the Markhamville reach, removing truckloads of waste.151

Figure 113. Bater Brook riddled with blown down trees following an over harvesting of timber. Photo A. White.....152

Figure 114. Donnelly Brook remains pristine but, any changes in the current land use this brooks will be at risk of becoming degraded. *Photo S. Prosser*.....153

List of Tables

Table 1. Priorities within watershed management based on classification and known hazards, on an eco-reach basis.....147

